



Lewiston-Porter Central School District 2020 Building Condition Survey



**TRAUTMAN
ASSOCIATES**

ARCHITECTS / ENGINEERS

TA Process - BCS

- Meetings with District Representatives to Review Each Building:
 - MEP (Mechanical, Electrical, Plumbing) engineers
 - Architects
 - Structural Engineer
 - Civil Engineer
- Team members complete field work after meeting.
- Team members review the following to assist with determining the age of the materials and equipment:
 - Existing as-built drawings
 - Last completed BCS
- Field notes/observations were analyzed and put into the BCS form.
- Meet with District representatives to review findings and get further input.
- Upload to SED by March 1, 2021

Name	Role, Years In Field
Brad V. Vaillancourt, AIA, CSI, LEED AP BD+C	Principal-in-Charge, 17
John W. Sisting, RA, LEED AP, NCARB	Project Manager, 20
Charles W. Moore, RA, LEED AP	Project Architect, 40
Paul R. Rosnak, PE	Mechanical/Plumbing Engineering, 40
Ivan McMillan, LC, LEED AP	Electrical Engineering, 40
Robert P. Stelianou, PE, F NSPE, LEED AP, CBIE	Civil/Structural Engineering, 40

2020 Building Condition Survey

2020 BUILDING CONDITION SURVEY - 2020

Building Information

Building Information

1. Name of school district
2. SED District 8-Digit BEDS Code
3. Building Name:
4. SED 4-Digit Facility Code:
5. Survey Inspection Date:
6. Building 911 Address:
7. City:
8. Zip Code:
9. Certificate of Occupancy Status:
 - ☐ A - Annual
 - ☐ T - Temporary
 - ☐ N - None

10. Certificate of Occupancy Expiration Date:

10a. Is this a manufactured building? (Relocatable, modular, portable)

- ☐ Yes
- ☐ No

Building Age, Gross Square Footage and Maintenance Staff

11. Building Age

	Year
Original Construction	
Addition #1	
Addition #2	
Addition #3	
Addition #4	
Addition #5	
Addition #6	

12. Square feet of construction

	Sq Feet
Original construction	
Addition #1	
Addition #2	
Addition #3	
Addition #4	
Addition #5	
Addition #6	

13. Gross square ft. of Building as currently configured:

14. Number of Floors:

15. How many full-time and part-time custodians are employed at the school (or work in the building)?

	Count Employees
Full-time custodians:	
Part-time custodians:	

2020 BUILDING CONDITION SURVEY - 2020

HVAC Systems

HVAC Systems

89. Heat Generating Systems (H)

- ☐ Yes
- ☐ No

89a. Heat generation source (check all that apply):

- ☐ Biomass
- ☐ Boiler / Hot Water
- ☐ Boiler / Steam
- ☐ Cogeneration Plant
- ☐ Electric
- ☐ Furnace / Forced Air
- ☐ Geothermal
- ☐ Heat Pump
- ☐ Unit Ventilation
- ☐ Other (describe below)

89a.1 Other heat generation source:

89b. Overall condition of heat generating systems:

- ☐ Excellent
- ☐ Satisfactory
- ☐ Unsatisfactory
- ☐ Non-Functioning
- ☐ Critical Failure

89c. Year of Last Major Reconstruction/Replacement:

89d. Expected Remaining Useful Life (Years):

89e. Cost to Reconstruct/Replace \$:

89f. Comments:

90. Ventilation System (exhaust fans, etc) (H)

- ☐ Yes
- ☐ No

90a. Type of ventilation system (check all that apply)

- ☐ Natural ventilation
- ☐ Central system
- ☐ Energy recovery ventilator
- ☐ Rooftop units
- ☐ Unitary (UVs, FC/BC, PTAC)
- ☐ Forced air furnace
- ☐ Heat pump
- ☐ Split system/ variable refrigerant
- ☐ Powered relief air system
- ☐ Gravity/barometric relief
- ☐ Other (specify)

90b. If "Other" please specify here

90c. Overall condition of ventilation systems

- ☐ Excellent
- ☐ Satisfactory
- ☐ Unsatisfactory
- ☐ Non-functioning
- ☐ Critical Failure

90d. Year of last major reconstruction/replacement

90e. Expected remaining useful life (years):

90f. Cost to reconstruct/replace \$:

90g. Comments

Building Condition Survey

2020 BUILDING CONDITION SURVEY - 2020

HVAC Systems

90. Ventilation System (exhaust fans, etc) (H)

- ☒ Yes
☐ No

90a. Type of ventilation system (check all that apply)

- | | |
|--|---|
| <input type="checkbox"/> Natural ventilation | <input type="checkbox"/> Heat pump |
| <input type="checkbox"/> Central system | <input type="checkbox"/> Split system/variable refrigerant |
| <input type="checkbox"/> Energy recovery ventilator | <input checked="" type="checkbox"/> Powered relief air system |
| <input type="checkbox"/> Rooftop units | <input checked="" type="checkbox"/> Gravity/barometric relief |
| <input checked="" type="checkbox"/> Unitary (UVs, FC/BC, PTAC) | <input type="checkbox"/> Other (specify) |
| <input type="checkbox"/> Forced air furnace | |

90b. If "Other" please specify here

90c. Overall condition of ventilation systems

- ☐ Excellent
☐ Satisfactory
☒ Unsatisfactory
☐ Non-functioning
☐ Critical failure

90d. Year of last major reconstruction/replacement: 2000

90e. Expected remaining useful life (years): 5

90f. Cost to reconstruct/replace: \$2,706,000

90g. Comments

Replace sixty-four (64) unit ventilators. Replace AHU serving Gym & Cafeteria. Relocate shop dust collector outside and provide fresh air. Add eight (8) range hoods in Home Economic Classrooms.

BCS Enhanced Services - Five Year Plan

Five Year Capital Facilities Plan

District Name: Lewiston-Porter Central School District

Building Name: Middle School

SID Number: 40-03-01-06-0-004


Units
LUMP SUM
EACH
SF = Square Feet
LF = Linear Feet

System Type
H = Health and Safety
S = Structure
C = Comfort
A = Aesthetic

System Rating
E = Excellent
S = Satisfactory
U = Unsatisfactory
NF = Non-Functioning
CF = Critical Failure

Cost Type
NEW = New Building
ADD = Addition
ALT = Alteration
MR = Major System Replacement
REP = Repair
ENG = Energy
MNT = Maintenance

Prepared by:

 **TRAUTMAN ASSOCIATES**
ARCHITECTS / ENGINEERS

Fall 2020

Line Number	Description	Priority	System Type	System Rating	Date of Last Major Reconstruction	Probable Useful Life Remaining	Cost Type	Quantity	Unit	Unit Cost	Total Cost Year 1 (2021)	Total Cost Year 2 (2022)	Total Cost Year 3 (2023)	Total Cost Year 4 (2024)	Total Cost Year 5 (2025)	Remarks
83-00	Interior Stairs		H	S	2000	10										
84-00	Elevators, Lifts and Escalators		H	U	2000	2										
84-01	Replacement of interior lift from the basement to the 1st floor	2	H	U		2	MR		LUMP SUM	\$132,000		\$132,000				The existing interior lift is old and repairing maybe difficult
85-00	Swimming Pool and Swimming Systems			NA												
86-00	Interior Bleachers			NA												
89-00	Heat Generating Systems		H	U	1991	5										
89-01	Cast iron steam boiler replacement	5	H	U		5	MR		LUMP SUM	\$363,000					\$363,000	Cast iron steam boiler near end of life expectancy
90-00	Ventilation System (exhaust fans, etc)		H	U	2000	5										
90-01	Unit ventilator replacement	5	H	U		5	MR	64	LUMP SUM	\$33,000					\$2,112,000	Nearing end of life expectancy
90-02	AHU/serving Gym & Cafeteria replacement	5	H	U		5	MR		LUMP SUM	\$330,000					\$330,000	Nearing end of life expectancy
90-03	Relocation of shop dust collector outside & provide air	5	H	U		5	ALT		LUMP SUM	\$198,000					\$198,000	
90-04	Add (3) range hoods in Home Economics Classroom	5	H	U		3	ADD		LUMP SUM	\$66,000					\$66,000	
91-00	Mechanical Cooling / Air-Conditioning Systems		H	U	2007	3										
91-01	Replacement of (10) PTAC units & split systems	3	H	U		3	MR		LUMP SUM	\$184,800			\$184,800			10 of 11 PTAC units & split systems near end of life expectancy
92-00	Piped Heating & Cooling Distribution Systems:		H	U	1982	2										
92-01	Steam pipe replacement	2	H	U		2	MR		LUMP SUM	\$1,650,000		\$1,650,000				Majority of steam piping is original (1957), numerous leaks & end of life expectancy
93-00	Ducted Heating & Cooling Distribution Systems		H	S	2000	10										Minimal duct system in gym, fitness and cafeteria
94-00	HVAC Control Systems		H	U	2000	5										
94-01	Upgrade pneumatic to all direct/digital controls	5	H	U		5	ALT		LUMP SUM	\$660,000					\$660,000	

Five Year Plan – Categories & Sortability

Five Year Capital Facilities Plan															
(Per Regulation 155.1(a)(4) and 155.3(c))															
District Name:	Niagara Wheatfield Central School District				System Type	H = Health and Safety S = Structure C = Comfort A = Aesthetic			System Rating	E = Excellent S = Satisfactory U = Unsatisfactory F = Failure I = Indeterminate			Cost Type	NEW = New Building ADD = Addition ALT = Alteration MR = Major System Replacement REP = Repair ENG = Energy MAINT = Maintenance	
Building Name:	Errick Road Elementary				BY SORTING THE DATA WE CAN LIST BY PRIORITY, COST TYPE, SYSTEM RATING, AND REPLACEMENT YEAR										
SED Number:	40-07-01-06-0-005										TYPE OF COST: SYSTEM REPLACEMENT REPAIR MAINTENANCE				
Line Number	Description	Priority	System Type	System Rating	Date of Last Major Reconstruction	Probable Useful Life Remaining	Cost Type	Quantity	Unit	Unit Cost	Total Cost 2014 / 2015	Total Cost 2015 / 2016	Total Cost 2016 / 2017	Remarks	
1															
2	00 - UTILITY COSTS														
3	Utility Cost: Natural Gas	N/A	N/A	N/A	N/A	N/A	ENG				\$82,569	\$101,560	\$124,919	Assume 25% yearly cost increase.	
4	Utility Cost: Electricity	N/A	N/A	N/A	N/A	N/A	ENG				\$159,583	\$178,733	\$200,181	Assume 12% yearly cost increase.	
5	Utility Cost: Water	N/A	N/A	N/A	N/A	N/A	ENG				\$6,112	\$6,418	\$6,738	Assume 5% yearly cost increase.	
6															
7	27 - SITE SANITARY	3	H	S	1948	5	REP	1	ump sum	\$5,000	0	0	0	\$5,000	
8															
9	30 - SITE ELECTRICAL		H												
10	Provide 1,200A, 3-Phase, 120/480V Electric Service	3	H	S	1999	5	REP	1	ump sum	\$17,000	0	0	0	\$17,000	
11	Replace 10 60A, 208V 3-Phase Disconnects	3	H	S	1999	5	REP	1	ump sum	\$22,000	0	0	0	\$22,000	
12	Replace 15 Canopy Lights and 15 Wall Poles	3	H	S	1999	5	REP	1	ump sum	\$15,000	0	0	0	\$15,000	
13															
14	40 - PAVEMENT		A	U	1980										
15	Reconstruct West Parking Lot	2	A	U	1980	2	REP	35,000	SF	\$6	0	\$210,000	0	0	
16	Reconstruct North Parking Lot bus loading/unloading	2	A	S	2006	2	REP	21,000	SF	\$6	0	\$126,000	0	0	
17															
18	41 - SIDE WALKS		A	U	1980										
19	Reconstruct Sidewalk Adjacent to West Parking lot	1	A	U	1980	1	REP	2,500	SF	\$6	\$15,000	0	0	0	
20	Reconstruct Sidewalk Adjacent to North Parking lot	1								\$6	\$24,000	0	0	0	
21											0	0	0	0	
22	49 - INTERIOR DOORS	3								\$31,000	0	0	0	\$31,000	
23														Replace All Non-ADA Knobs on Classroom Doors	
24	52 - INTERIOR ELEC. DISTRIBUTION		H	S	1989										
25	Replace 7 Panels	3	H	S	1989	5	REP	1	ump sum	\$120,000	0	0	0	\$120,000	
26	Replace 50 Duplex Receptacles	3	H	S	1989	5	REP	1	ump sum	\$5,000	0	0	0	\$5,000	
27															
28	53 - LIGHTING FIXTURES		A	S	1999						0	0	0	0	
29	Replace 50 Light Switches	3	A	S	1999	5	REP	1	ump sum	\$5,000	0	0	0	\$5,000	
30	Provide Occupancy Sensors	3	A	S	1999	5	REP	1	ump sum	\$13,000	0	0	0	\$13,000	
31														In closets and bathrooms	
32	54 - COMMUNICATIONS	3	H	S	1999	5	REP	1	ump sum	\$155,000	0	0	0	\$155,000	
33														Replace Public Address System & Security Upgrades including Inter. Gym	
34	61 - EXTERIOR WALLS/COLUMNS		S	S											
35	Repair Selected Areas of Exterior Walls	3	A	S	2001	5	REP	2,500	SF	\$35	0	0	0	\$87,500	
36	Replace Deteriorated Metal Panels	3	A	S	2001	5	REP	80	SF	\$250	0	0	0	\$20,000	
37	Recoat EIFS System	3	A	S	2001	5	REP	1	ump sum	\$52,500	0	0	0	\$52,500	
38														Including sealant replacement	
39	68 - ROOFS	3	S	S	2008	5	REP	35,850	SF	\$35	0	0	0	\$1,255,000	
40														Replace portion of roof	
41	72 - PLUMBING DRAINAGE	3	H	S	1989	5	REP	1	ump sum	\$45,000	0	0	0	\$45,000	
42														Replace Sanitary and Storm Cross Connection	
43	72 - HOT WATER HEATERS	3	H	S	1989	5	REP	1	ump sum	\$58,000	0	0	0	\$58,000	
														Replace Hot Water Heaters	

SAMPLE OF SYSTEMS DATA

SAMPLE OF
SYSTEMS
DATA

BCS Enhanced Services

— Roof Inspection and Thermal Roof/Moisture Scan (MS, HS, IEC, PEC, CRC, MB)



All roofs on the Lewiston Porter Central School District were inspected and infrared scanned in June 2020 in coordination with Trautman Associates and the District. Approximately 422,000 square feet of roofing was inspected.

Roof Core Construction

- Since all EPDM single ply membrane roofs are under existing warranties, no core samples were taken during the inspections.

Inspection Findings


- Maintenance Building
 - Overall condition: Good.
 - Roof Drain Strainers: Clean.
 - Ponding: None noted.
- Community Resource Center
 - Overall condition: Fair-to-Good.
 - Roof Drain Strainers: Heavily clogged with debris and preventing drainage.
 - Ponding: Caused by clogged roof drains.
 - Low flashing heights (6") along walls.
 - Several punctures/slices and one large seam failure noted in EPDM.
- Primary Education Center
 - Overall condition: Fair-to-Good.
 - Roof Drain Strainers: Clogged with debris and preventing drainage.
 - Ponding: Caused by clogged roof drains.
 - Low heights at masonry through-wall flashings.
 - Two completely loose metal curb caps not attached to their rail curbs.
 - Extremely low vent pipes (3" above roof) noted.
 - Several punctures and one open EPDM seam noted.

TREMCO Roof Analysis Report

Page



HS, Wet Area #3 (66 Sq. Ft.) with puncture circled within wet area.



HS, Thermal image of Wet Area #3.

TREMCO Roof Analysis Report

Page 48 of 48



Debris pile of old scaffolding parts should be removed from the roof surface.




MS, Many drains were severely clogged on the Middle School roofs.

TREMCO Roof Analysis Report

Page

Infrared Moisture Survey Findings

- Middle School
 - 18 wet insulation areas located.
 - Total of 994 square feet wet insulation.
 - Punctures noted in wet areas 4, 12, 13, 16, 17.



TREMCO Roof Analysis Report

Page 7 of 48

BCS Enhanced Services

– Stage Rigging and Lighting Inspection (IEC & HS)



SYRACUSE SCENERY & STAGE LIGHTING CO., INC.

STAGE RIGGING SYSTEMS SURVEY REPORT
LEWISTON PORTER CENTRAL SCHOOL DISTRICT
INTERMEDIATE EDUCATION CENTER
YOUNGSTOWN, NEW YORK
SURVEY DATE: 8/13/20

A. SITE SURVEY CRITERIA

1. Qualifications of the inspector
 - a. The survey was conducted by Harold (Ike) Shi experience in the design, installation, maintenance theatrical rigging systems.
 - b. Ike Shippers is an ETCP-certified Stage Rigger
2. General survey scope
 - a. Moving or static rigging systems used to move luminaries and other related equipment.
 - b. Stage track systems
 - c. Stage curtains
 - d. Survey is conducted from the stage floor. No performed. No structural or architectural review.
 - e. The suitability of the buildings to properly handle loads imposed by the rigging systems is beyond the scope of this report.
3. Systems survey scope
 - a. System hardware was observed for suitability
 - b. Moveable rigging systems were operated throughout the available range of travel and
 - c. Tracks were observed to determine that they are for use and functionality.
 - d. Stage curtains were observed for overall condition indicating up to date flame retardancy information

B. LEWISTON PORTER INTERMEDIATE EDUCATION CENTER

1. GENERAL SYSTEM INFORMATION
 - a. The approximate date of the original installation
 - b. The rigging system includes 2 static hung sets
 - c. Static hung system information
 - 1) Batten length: 34'-6" main valance batten
 - 2) Batten attachment: batten is suspended with
 - 3) Attachment spacing: 7'
 - 4) Number of batten attachments: 5 on valance

SYRACUSE SCENERY & STAGE LIGHTING CO., INC.

- 5) Batten size: 1-1/4" schedule 40 batten
- 6) Batten splicing: pipe coupler
- d. Manual counterweight system information
 - 1) Guide type: wire guide
 - 2) Lift lines per set: 4
 - 3) Set centers: 6"
 - 4) Cable type: 3/8" 6x7 Improved plow wire
 - 5) Cable fittings: malleable cable installed by
 - 6) Batten size and splices: 1-1/4" schedule 40
 - 7) Batten attachment: clove hitch with twist
 - 8) Batten attachment spacing: 7', 14', 7'
 - 9) Handline type: 5/8" Manila
 - 10) Head block orientation: underhung with a
 - 11) Loft block orientation: underhung
 - 12) Number of locking rails: 2 locking rail
 - 13) Locking rail rope lock spacing: 6"
 - 14) Rope lock type: short handle
 - 15) Counterweight size: 4"

2. OVERALL EVALUATION:

- a. System is in very poor condition.
- b. The static hung system is suspended with jack suspension. The jack chain should be replaced
- c. Batters use pipe couplers to splice pipes together used. Internal batten sleeving should be used entire length of the batten.
- d. Head block sheave is an uneven pitched sheave head block sheave.
- e. Operating and warning signage is missing.
- f. Maintenance and service log was not available
- g. Batters are missing batten end caps. These are end of the pipe batten to give a visual signal of a softer surface to come into contact with the batten.
- h. The cable and cable fittings in the system is unsafe
- i. Loft blocks and head blocks have no bearings wearing out and making noise.
- j. More investigation is needed to see about and increase the number of pickup points on the batten below the center beam that may need to be increased

SYRACUSE SCENERY & STAGE LIGHTING CO., INC.

- k. Stage curtains have reached their serviceable life and serious consideration should be given to replace the curtains.
- l. Handline in the curtain tracks needs to be replaced. The current handline is manila that has become dry rotted and is giving off splinters while being used.
- m. Counterweight arbors have cast iron tops and loose nuts on the arbor rods. These arbors should be replaced.
- n. Floor blocks in the counterweight system have bushing rather than bearing and are making noise during operation.
- o. Rope locks are very worn and some do not function.
- p. The locking rail is constructed with nuts and bolts that have become loose over time. A new locking rail should be installed with welded connections.
- q. The school district should ensure that all of the personnel who operate the counterweight rigging systems have been trained for its use.

Page 1

101 Monarch Drive Liverpool, NY
 p: 315-453-8096, 800-453-7775 f: 315-453-7897
 e: ishippers@syracusescenery.com

Page 2

101 Monarch Drive Liverpool, NY
 p: 315-453-8096, 800-453-7775 f: 315-453-7897
 e: ishippers@syracusescenery.com

Page 3

101 Monarch Drive Liverpool, NY 13088-4514
 p: 315-453-8096, 800-453-7775 f: 315-453-7897 www.syracusescenery.com
 e: ishippers@syracusescenery.com

BCS Enhanced Services

– Kitchen Investigation (MS, HS, IEC, PEC)

Leviston Porter Central School
Food Service Equipment - Existing Conditions Report
August 2020

Page 6 of 21



Roth Consulting Gr

Leviston Porter Central School
Food Service Equipment - Existing Conditions Report
August 2020

Page 18 of 21

High School

Grades 9-12
Construction and opened in 1962, renovated in 2015.
6" jacket - 10.53 to 11.26
8" jacket - 11.39 to 12.21
7" jacket - 12.25 to 13.07

The overall kitchen space is large and open. The back section was dedicated to walk-in while we were on site. It appears some of the equipment is from previous renovations 1997 or installed during the 2015 renovation. Other pieces of equipment appear older.

Equipment recommendations:

- Independent hand washing sinks are required.
- Remove and replace cooking equipment that does not work.
- Replace the two existing hoods to better meet today's needs.
- Vegetable preparation sink to contain an indirect waste to a floor sink.
- Replace work tables and shelving units that are galvanized steel and not safe.

Room finish materials:

- Ceiling tile: there is currently a mix of washable / cleanable tile and acoustical; should all be changed to washable / cleanable.
- Wall partition between the kitchen and dry storage area requires a cove base.
- Deep cleaning of the dish room floor is required to remove delugeants and lime.
- The remaining walls and floor materials appear to be in good condition.

Existing Equipment Condition Observations

Refrigerated Holding:

- The existing walk-in cooler / freezer have some wear although are still in good condition.
- The refrigeration piping insulation is not complete around the pipe hangers. TI to be corrected.
- Remaining reach in refrigeration appears to be in good condition. Recommend replacing door gaskets as needed. Recommend installation of back comping housing covers where exposed to the kitchen.

Exhaust cooking center:

- The main center island exhaust hood may have been added in the 1970's and appears to be new to within the 1997 or 2015 renovation. This hood appears to water light season. This fire suppression system is outdated and connect with the gasline and ranges.

Roth Consulting G

Low Port High School
Food Service New Equipment Budget

August 2020
Study Budget

Page 1 of 1

- General Notes:**
1. All F.S.C. is Not in Food Service Contract.
 2. Budget costing is for Food Service Equipment only and does not include modifications to the room, building structure, existing equipment or service connections.
 3. Budget costing is reflective of equipment shown on associated sketch and floor plan drawing. Accessories have been added as required for a complete equipment unit.
 4. Small ware items (pots, pans, dishes, appliances, etc.) are not included in the estimated budget numbers below. All small ware equipment is to be purchased outside this contract.
 5. Service connections (plumbing and electrical building services) are not included in the costing noted.


Item	Description	Qty.	Equipment Cost Estimate
Hand Sink		3	3,820.00
Snap & Paper Towel Dispenser		3	N/L F.S.C.
Pa. Rack Shaking Units		2	600.00
Work Top Table		2	5,000.00
Double Connection Oven		2	45,800.00
Occupant Monitor		2	25,000.00
Ranges, Four burner		2	23,000.00
Risk Cooker, 8 coils		2	5,500.00
Free Holding Cabinets		2	8,500.00
Work Table w/ sink		2	5,500.00
Free Vent Hot Heat Counter		2	20,150.00
Serving Counter, Hot Top		2	9,475.00
Cold Food Serving Counter		2	15,500.00
Vac Drain Cabinet		2	8,000.00
Free 3-1/2 w/ Partition		2	2,000.00
Refrigerated Merchandiser		2	20,000.00
Cash Register Stand		2	8,750.00
Cash Register		2	N/L F.S.C.
Serving Counter, Continental Stand		2	15,870.00
Cook Burner, 40"		1	75,000.00
Exhaust Duct		1	9,000.00
Dish Compartment Sinks		1	5,000.00

Equipment Budget Cost - Mobile School
12% Estimated Delivery Service Fee
1% Estimated Freight

Total Food Service Equipment Budget:

\$24,106.40

Roth Consulting Group, Inc.



Leviston Porter High School
Food Service Equipment Study
August 2020

Page 1 of 1

Equipment	Manufacturer	Model No.	Serial No.	Age	MEP Information	General Condition	Notes
Refrigerator Number							
1	GE	20LNR	14053	1993	120V/1PH/2.0GAMPS	GOOD	Unit is still in use but is an older model.
2	GE	20LNR	14053	1993	120V/1PH/2.0GAMPS	GOOD	Unit is still in use but is an older model.
3	GE	20LNR	14053	1993	120V/1PH/2.0GAMPS	GOOD	Unit is still in use but is an older model.
4	GE	20LNR	14053	1993	120V/1PH/2.0GAMPS	GOOD	Unit is still in use but is an older model.
5	GE	20LNR	14053	1993	120V/1PH/2.0GAMPS	GOOD	Unit is still in use but is an older model.
6	GE	20LNR	14053	1993	120V/1PH/2.0GAMPS	GOOD	Unit is still in use but is an older model.
7	GE	20LNR	14053	1993	120V/1PH/2.0GAMPS	GOOD	Unit is still in use but is an older model.
8	GE	20LNR	14053	1993	120V/1PH/2.0GAMPS	GOOD	Unit is still in use but is an older model.
9	GE	20LNR	14053	1993	120V/1PH/2.0GAMPS	GOOD	Unit is still in use but is an older model.
10	GE	20LNR	14053	1993	120V/1PH/2.0GAMPS	GOOD	Unit is still in use but is an older model.
11	GE	20LNR	14053	1993	120V/1PH/2.0GAMPS	GOOD	Unit is still in use but is an older model.
12	GE	20LNR	14053	1993	120V/1PH/2.0GAMPS	GOOD	Unit is still in use but is an older model.
13	GE	20LNR	14053	1993	120V/1PH/2.0GAMPS	GOOD	Unit is still in use but is an older model.
14	GE	20LNR	14053	1993	120V/1PH/2.0GAMPS	GOOD	Unit is still in use but is an older model.
15	GE	20LNR	14053	1993	120V/1PH/2.0GAMPS	GOOD	Unit is still in use but is an older model.
16	GE	20LNR	14053	1993	120V/1PH/2.0GAMPS	GOOD	Unit is still in use but is an older model.
17	GE	20LNR	14053	1993	120V/1PH/2.0GAMPS	GOOD	Unit is still in use but is an older model.
18	GE	20LNR	14053	1993	120V/1PH/2.0GAMPS	GOOD	Unit is still in use but is an older model.
19	GE	20LNR	14053	1993	120V/1PH/2.0GAMPS	GOOD	Unit is still in use but is an older model.
20	GE	20LNR	14053	1993	120V/1PH/2.0GAMPS	GOOD	Unit is still in use but is an older model.
21	GE	20LNR	14053	1993	120V/1PH/2.0GAMPS	GOOD	Unit is still in use but is an older model.

Date: August 18, 2020
By:

Roth Consulting Group, Inc.

Top Findings at Each Building

- Middle School
- Intermediate Education Center
- Primary Education Center
- High School
- Community Resource Center
- Maintenance Building



2017 CIP
HS Guidance Offices & Running Track

Middle School

- Parking Lot, Roadways, and Sidewalk Reconstruction - \$792k
- Exterior and Interior Door Replacements - \$805k
- Window Replacements – \$1.84m
- Boiler and Steam Piping Replacement - \$363k
- Unit Ventilator & RTU Replacement - \$2.44m
- Mechanical Cooling/AC System - \$185k
- Steam Piping Replacement - \$1.65m
- HVAC Control Upgrades - \$660k
- Kitchen Upgrades - \$1.06m
- Crawlspace Ventilation - \$80k



Intermediate Education Center

- Parking Lot and Sidewalk Reconstruction - \$1.75m
- Interior Door Replacements - \$354k
- Boiler Replacement - \$330k
- AHU & RTU Replacement - \$528k
- Split System Replacement - \$66k
- Steam Condensate Piping Replacement - \$1.45m
- Radiator and Convactor Replacement - \$528k
- HVAC Control Upgrades - \$488k
- Phone & PA System Upgrade - \$179k
- Boys and Girls Locker Rooms - \$1.58m
- Kitchen Upgrades - \$1.06m
- Crawlspace Ventilation - \$80k



Primary Education Center

- Parking Lot, Roadways, and Sidewalk Reconstruction - \$528k
- Masonry Wall and Foundation Repairs - \$607k
- Window Replacements - \$1.76m
- Interior Door Replacements - \$449k
- Boiler Replacement - \$264k
- Water and Sanitary Piping Replacements - \$290k
- Phone & PA System Upgrade - \$179k
- Boys and Girls Locker Rooms - \$868k
- Kitchen Upgrades - \$924k
- Crawlspace Ventilation - \$132k



High School

- Athletic Field Lighting Replacement - \$1.45m
- Parking Lot, Roadways, and Sidewalk Reconstruction - \$3.07m
- Synthetic Turf Replacement - \$750k
- Masonry Wall Repairs - \$430k
- VCT Replacement in A-Wing - \$231k
- HC Access to Seating in Pool - \$330k
- Heat Exchange Replacement - \$132k
- Plumbing Fixture Replacements - \$495k
- Kitchen Upgrades - \$1.06m
- Crawlspace Ventilation - \$158k



Community Resource Center

- Parking Lot & Roadways Reconstruction - \$726k
- Gym AHU & Exhaust Fan Replacement - \$158k
- Cooling / AC - \$142k
- HVAC Control Upgrades - \$66k
- Analog Phone System Upgrade - \$26k



Maintenance Building

- Parking Lot & Roadways Reconstruction - \$475k



Police Building

- Fire Alarm Replacement - \$60k
- Roof Replacement - \$175k
- RTU Replacement - \$75k



Grand Total =	\$36,322,025
----------------------	---------------------

Questions?



*2017 CIP
High School - Commons Area*